

UI FLOOR PTE LTD

GST Reg. No.: 201534108D
 2 Yishun Industrial Street 1, #05-20
 Northpoint Bizhub, Singapore 768159

Mobile: +65 9189 0926 (Jennifer Neo)

Tel. No.: +65 6208 0135/ +65 6208 0136

Fax No.: +65 6208 0137

E-mail: u1floor@gmail.com



#RMET# Remastered Engineered Timber

- 1 **Core - Magnesium Oxide**
- 2 **100% Waterproof**
- 3 **100% Termite Free**
- 4 **Floating System**
- 5 **Zero Adhesive**
- 6 **Zero Nail**
- 7 **Installation (5x) Faster**
- 8 **Easy Reinstatement / Replacement**
- 9 **Cushion Backing**
- 10 **Premium Feel**
- 11 **Sound Reduction**
- 12 **High Density**
- 13 **7 - Layers Premium UV Lacquered**
- 14 **Weight - 5x Heavier than Traditional Engineered Timber**



Traditional Type Engineered Timber

- 1 Core - Multi Layers of Plywood
- 2 Prone to Scratches
- 3 Prone to Termites
- 4 100% Glue Down with Adhesive
- 5 Requires Nailing for every planks
- 6 Time Consuming for Installation
- 7 Higher cost for Reinstatement
- 8 Requires good / higher cost of Adhesive
- 9 Tedious Procedure and Additonal Cost Incurred when comes to Replacement / Reinstatement
- 10 2 Layers of UV Coating only



Solid Timber

- 1 Minimum time for Installation: 3 to 4 weeks
- 2 Time Consuming for Installation
- 3 Noisy Work that requires Night Job
- 4 Able to do multiple Re-sand and Re-varnish at additional cost
- 5 Solid Timber material cost is much higher and uncertain due to unstable in supply chain
- 6 2 Layers of Water Based / Solvent Based Coating on Site
- 7 Prone to Scratches
- 8 Prone to Termites
- 9 100% Glue Down with Adhesive
- 10 Requires Nailing for every planks
- 11 Higher cost for Reinstatement further more needs to make good
- 12 Requires good / higher cost of Adhesive
- 13 Tedious Procedure and Additonal Cost Incurred when comes to Replacement / Reinstatement